

UTICA CITY SCHOOL DISTRICT

320 Elizabeth Street
Utica, NY 13501

Michael M. Ferraro
Maintenance Foreman
mferraro@uticaschools.org

Ph. (315) 792-2214
Fax. (315) 792-2260

November 14, 2016

Dear Parents & Guardians: Kernan Elementary School

On September 6, 2016, Governor Cuomo signed new legislation requiring the testing of drinking water in New York public schools for lead levels. The new legislation is explained in a document entitled: "State Department of Health Issues New Regulations to Mandate Lead Testing in New York Elementary Schools by October 30th, and in the Secondary Schools by October 31st; New York is the First State in the Nation to Complete Lead Testing in All School Districts by the End of 2016." To access this document, please visit the following link:

<https://www.governor.ny.gov/news/governor-cuomo-signs-landmark-legislation-test-drinking-water-new-york-schools-lead>

The regulations adopted by the N.Y.S. Department of Health require that a public school take samples from all water outlets in each of its buildings to ascertain whether any lead readings in the water exceed the state required "action-levels." A "water outlet" is defined as a potable water fixture currently or potentially used for drinking or cooking purposes, including, but not limited to, bubblers, drinking fountains, and faucets.

In anticipation of this legislation, we have tested all applicable water fixtures to test for lead levels. A full Comprehensive Report of the sampling program is available on the school's website: <http://www.uticaschools.org/kernan>.

There were 79 water fixtures tested; and 13 showed lead levels above the allowable 15 ppb (parts per billion) marks:

Location: Auditorium - Girls Bathroom, .017

Remediation: Replaced faucet; posted sign reading: "Do Not Drink – Hand Washing Only"

Location: Rm. 103 – Bathroom Sink, .016 ppb

Remediation: Replaced faucet; posted sign reading: "Do Not Drink – Hand Washing Only"

Location: Rm. 101 – P.E. Office – Bathroom Sink, .224 ppb

Remediation: Replaced faucet; posted sign reading: "Do Not Drink – Hand Washing Only"

Location: Rm. 138 – Bathroom Sink, .035

Remediation: Replaced faucet; posted sign reading: "Do Not Drink – Hand Washing Only"

Location: Rm. 135 – Bathroom Sink #2, .020


Remediation: Replaced faucet; posted sign reading: "Do Not Drink – Hand Washing Only"

- Location: Rm. 143 – Bathroom Sink, .035 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”
- Location: Rm. 116B (Principal’s Bathroom) – Bathroom Sink, .0155 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”
- Location: Fountain across from Rm. 203 – Drinking Fountain, .048 ppb
Remediation: Taken out of use.
- Location: Rm. 208A – Classroom Sink #1, .027 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”
- Location: Rm. 208A – Classroom Sink #2, .074 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”
- Location: Rm. 235 – Classroom Sink, .027 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”
- Location: Rm. 024A – Closet - Bathroom Sink, .059 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”
- Location: Rm. 020 – Closet - Custodial Sink, .080 ppb
Remediation: Replaced faucet; posted sign reading: “Do Not Drink – Hand Washing Only”

We have already addressed the outlets which tested in excess of state requirements by temporarily shutting off the drinking fixtures impacted and posting signage that alerts students and staff to avoid drinking the water from these outlets. It should be noted that under the State’s regulations, the water from these outlets could still be used for handwashing and cleaning purposes. We will conduct a second sampling of water from these fixtures. Official re-testing results should be available within 4 to 6 weeks. If as a result of a second testing the lead levels in the potable water sources are found to exceed state requirements, a remediation plan will be put into place to correct these deficiencies. In the interim, the district will continue to insure that all those using each of our school buildings will be provided with an adequate supply of water for drinking and cooking. We will send a second letter to you regarding those results, and post them to our website as well.

If you should have any questions on the above at any time, please feel free to contact me on my office phone: (315) 792-2231.

Thank you,



Michael M. Ferraro
Maintenance Foreman

cc: Bruce Karam – Superintendent of Schools
Lori Eccleston – Dir., Curriculum & Instruction, K-12
Mary Kay Van Dreason – Dir., Food Service
Alicia Mroz – Admin. for Pre-K/Student Programs
Building Principal
FILE: Lead-In-Water 2016