

# Water Survey

District: Utica CSD  
 Building: Kernan Elementary  
 Survey Date: 9/21/16

Space ID	Location	(A) Bathroom Sink	(B) Classroom Sink	(C) Kitchen Sink	(D) Science Rm Sink	(E) Custodial Sink	(F) Drinking Fountain	(G) Hose Bibb	(H) Ice Chest
1	Rm 017					1			
2	Rm 017a	1							
3	Rm 022 outside of						1		
4	Rm 022a Switch Rm		1						
5	Rm 024a Closet					1			
6	Rm 020 Closet					1			
7	Rm 010a Janitor Closet					1			
8	Rm 010 Boys Bathroom	2							
9	Rm 009 Girls Bathroom	2							
10	Rm 012 Outside Storage						1		
11	Rm 008 Garage		1						
12	Rm 001a					1			
13	Rm 002 Kitchen			2					
14	Rm 223 off 225			1					
15	Fountain outside 232a						1		
16	Rm 232 Boys Toilet	3							
17	Rm 232a					1			
18	Rm 239 Girls Toilet	3							
19	Fountain - near 239						1		
20	Rm 242a	1							
21	Rm 235		1						
22	Rm 218 Boys Toilet	4							
23	Rm 218a Janitor					1			
24	Rm 208a		2						
	Fountain across from 203								
25	Music						1		
26	Rm 206 Girls Toilet	5							

27	Rm 209C off stage		1						
28	Rm 210a Faculty Toilet	1							
29	Rm 116b in 116 Principal	1							
30	Fountain outside 120						1		
31	Fountain near Mens Toilet #135						1		
32	Rm 132a Janitor				1				
33	Rm 134b Toilet in 134	1							
34	Rm 134		2				2		
35	Rm 135	2							
36	Fountain opposite 136d						1		
37	Rm 143	1							
38	Fountain after stairs/146						1		
39	Rm 149	1							
40	Rm 148a across 148	1							
41	Rm 145	1							
42	Rm 142 Girls Toilet	2							
43	Rm 139 Boys Toilet	4							
44	Rm 139b Janitor				1				
45	Rm 138	1							
46	Rm 132 Boys Toilet	4							
47	Rm 114 Nurse	1							
48	Rm 113 Girls Toilet	5							
49	Fountain at 110 Health						1		
50	Fountain in Gym						2		
51	Rm 103 Toilet	1							
52	Rm 101 P.E. Office	1							
53	Rm 105 Janitor near 106				1				
54	Boys Locker Rm 107	2							
55	Girls Locker Rm 108	2							
56	<b>Individual Totals</b>	<b>53</b>	<b>8</b>	<b>3</b>	<b>0</b>	<b>10</b>	<b>14</b>	<b>0</b>	<b>0</b>
57									
58	<b>Building Total</b>	<b>88</b>							