

Water Survey

District: Utica CSD

Building: Conkling Elementary

Survey Date: 9/12/16

Space ID	Location	(A) Bathroom Sink	(B) Classroom Sink	(C) Kitchen Sink	(D) Science Rm Sink	(E) Custodial Sink	(F) Drinking Fountain	(G) Hose Bibb	(H) Ice Chest
1	Rm 102		1	3					
2	Rm 104	3							
3	Rm 106	1							
4	Rm 133						2		
5	Rm 112					1			
6	Rm 111	1							
7	Rm 122	2							
8	Rm 132					1			
9	Rm 133b						2		
10	Rm 125	1							
11	Rm 127	3							
12	Rm 223a	1							
13	Rm 221	1							
14	Rm 229b						2		
15	Rm 211					1			
16	Rm 219	4							
17	Rm 220	1							
18	Rm 218b	1							
19	Rm 229a						1		
20	Rm 208a	1							
21	Rm 209	2							
22	Rm 204	1							
23	Rm 202	1							
24	Rm 216a	1							
25	Rm 214a	1							
26	Rm 320	1							
27	Rm 318					1			

28	Rm 316	2							
29	Rm 317a	1							
30	Rm 315b	1							
31	Rm 327a						1		
32	Rm 311b	1							
33	Rm 310	2							
34	Rm 308					1			
35	Rm 306	1							
	Individual Totals	35	0	0	0	5	8	0	0
	Building Total	48							