

# Water Survey

District: Utica CSD  
 Building: Jefferson Elm.  
 Survey Date: 09/13/2016

Space ID	Location	(A) Bathroom Sink	(B) Classroom Sink	(C) Kitchen Sink	(D) Science Rm Sink	(E) Custodial Sink	(F) Drinking Fountain	(G) Hose Bibb	(H) Ice Chest
1	Fountain by Lobby						1		
2	Rm 104	1							
3	Rm 104		1				1		
4	106		1				1		
5	106a	1							
6	173a					1			
7	107			1					
8	Rm 112	1					1		
9	Rm 114		1				1		
10	Rm 114	1							
11	Rm 116		1				1		
12	Rm 116	1							
13	Rm 118		1				1		
14	Rm 118	1							
15	Rm 117		1				1		
16	Rm 117	1							
17	Rm 115		1				1		
18	Rm 115	1							
19	Rm 113		1				1		
20	Rm 113	1							
21	117	1							
22	Rm 111	1							
23	122			1					
24	Principals	1							
25	102a & 102	1	2						
26	Restroom	1							
27	Rm 145	1							

28	125	1							
29	Rm 149		1						
30	154		1						
31	159	3							
32	160	3							
33	D. Fountain						2		
34	Rm 154		1						
35	152		1						
36	Girls	5							
37	Boys	5							
38	Faculty Rm			1					
39	Art Room		3						
40	Rm 140		1						
41	Rm 138		1						
42	Rm 136	1	1				1		
43	Rm 135		1						
44	Rm 137		1						
45	Rm 139		1						
46	132 Custodial Key won't work					1			
47	Girls Bathroom	5							
48	Boys Bathroom	5							
49	130					1			
50	129c			2					
51	Rm 205		1				1		
52	Rm 205	1							
53	207		1				1		
54	207a	1							
55	Rm 209		1				1		
56	Rm 209	1							
57	Rm 211		1				1		
58	Rm 211	1							
59	Rm 210		1				1		
60	Rm 210	1							
61	Rm 208		1				1		
62	Rm 208	1							
63	Rm 206		1				1		

64	Rm 206	1							
65	Rm 201		1				1		
66	Rm 201	1							
67	210 Rm 213	1	1				1		
	<b>Individual Totals</b>	<b>43</b>	<b>23</b>	<b>5</b>	<b>0</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>
	<b>Building Total</b>	<b>86</b>							